



ADDENDUM NO. 2
Issued November 5, 2024

TO

REQUEST FOR PROPOSALS

**For Engineering, Procurement and Major Salvage Operations
Management Services for the Hartford Resource Recovery
Facility, Jet Turbine Facility and South Meadows Site**

(RFP Number 25-AUTH-002)

Note: Entities submitting a Proposal are required to acknowledge this and all Addenda in Section 4 of the Proposal Form.

This Addendum #2 constitutes the additional information concerning the Site tour to be provided by the Authority to all Proposers expressing interest in this RFP approximately forty-eight hours prior to the tour as specified in Section I.F. of the RFP.

1. SITE TOUR ATTENDANCE AND EXPRESSIONS OF INTEREST

If they have not already done so, prospective proposers interested in attending the site tour on November 7, 2024 - as specified in Section I.F. of the RFP - should submit their contact information and expression of interest in the manner specified in Section I.D. of the RFP.

2. NUMBER OF ATTENDEES FROM EACH FIRM

The MIRA Dissolution Authority (the “Authority”) requests that prospective proposers attending the site tour limit themselves to not more than 3 attendees per firm.

3. ARRIVING FOR SITE TOUR

Attendees of each site tour should plan to meet at 300 Maxim Road, Gate 70 (the last gate on the left on the Maxim Road cul-de-sac across from Brainard Airport). In the event that the gate is closed, there is a call box at the gate and Authority staff can remotely open the gate for entry. Once on site, attendees should park their vehicles in the office parking lot, proceed to the Authority’s headquarters office (the former Waste Processing Facility Operator offices) and sign in with the front desk. The Authority expects to conduct a brief overview (RFP overview, safety overview, etc.) in the headquarters conference room before proceeding with the tour of the site.

During the tour of the Site, Authority personnel will provide a high level overview and tour of installed equipment at the Waste Processing Facility, Power Block Facility, Jet Turbine Facility and ancillary buildings. A map of the expected tour route is attached. This tour is expected to be primarily a walking tour, including a mile or more loop among and within the buildings.

4. SITE TOUR PERSONAL PROTECTIVE EQUIPMENT

The Authority requests that Attendees of the site tours bring personal protective equipment (“PPE”) as specified on the attached flier (attached hereto and incorporated herein this Addendum 2). The Authority will have limited supplies of some PPE available to borrow (e.g. hard hats and safety vests), but attendees are encouraged to bring their own to ensure adequate supply.

5. ADDITIONAL INFORMATION REGARDING DOCUMENTS REFERENCED IN THE RFP

Section I.B. of the RFP makes reference to two documents for which more information can be found on the Authority’s website at the links herein:

- The Authority’s Draft Closure plan and correspondence related thereto can be found at <https://www.ctmira.org/records-reports/additional-communications/closure-plan>.
- The Authority’s Hazardous Building Materials (“HBM”) Survey is a portion of a broader South Meadows Redevelopment Considerations Study currently underway. The final

HBM Survey report is expected to be available by the end of the calendar year. More public information regarding this Study can be found on the Authority's website at <https://www.ctmira.org/home/south-meadows-redevelopment-considerations-study>

- END OF ADDENDUM 2 (attachment follows) -

- **Site tour PPE flyer**
- **Site tour expected route map**

Minimum PPE Requirements for WPF/PBF Visitation



Listed below are the minimum requirements for visiting or touring the WPF and PBF facilities. There is a limited number of hardhats, safety glasses, and safety vests that can be provided for your use if you do not have your own. All other requirements must be met or you will be denied access to the facilities.

1. Long pants.




2. Long sleeve shirts.



3. Minimum of leather upper hard sole shoes.



4. Safety glasses or glasses with side shields



5. Hardhat



6. Safety Vest



TOUR ROUTE

- 1) Start MSW Processing Lines
- 2) Central Processing Area
- 3) Start RDF Conveyors
- 4) Thermal Oxidizer
- 5) Fuel Conveyors (RDF+Coal)

- 6) Jet Peaking Units
- 7) 500,000 Gallon Fuel Tank
- 8) Post Combustion Air Handling
- 9) Steam Turbine Hall
- 10) Boiler Area

